




RJ11 / RJ12



USB pinouts for voltage sensor



Connecting RJ11 to motion sensor



RS485

